

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		800FM02Z		

D. Failure History -
E. Ground Turnaround -
Heater functional test and heater circuit quantitative resistance test.

F. Operational Use -
1. Crew Response -
Pre-EVA/Post EVA: Troubleshoot problem. If no success, terminate EVA.

EVA: If loss of fingertip heating occurs in one glove, turn off power to the glove, terminate EVA. If loss of fingertip heating occurs in both gloves, turn off power from battery, terminate EVA.


2. Special Training -
None.


3. Operational Considerations -
Not Applicable.


EXTRAVEHICULAR MOBILITY UNIT
SYSTEMS SAFETY REVIEW PANEL REVIEW
FOR THE
I-800 SEMU HARNESS
CRITICAL ITEM LIST (CIL)


EMU CONTRACT NO. NAS 9-97150


Prepared by: 
HS - Project Engineering


Approved by:  2/14/02
NASA - SSA/SSM


HS - Reliability

 5/21/02
NASA - EMU/SSM

 4/24/02
HS - Engineering Manager

 5/24/02
NASA - S & MA


NASA - MOD

 6/04/02
NASA - Crew

 6/3/02
NASA - Program Manager

EXTRAVEHICULAR MOBILITY UNIT
 SYSTEMS SAFETY REVIEW PANEL REVIEW
 FOR THE
 I-800 SEMU HARNESS
 CRITICAL ITEM LIST (CIL)
 EMU CONTRACT NO. NAS 9-97150

Prepared by: *[Signature]*
 HS - Project Engineering

Approved by: *[Signature]*
 NASA - SSA/SSM

[Signature]
 HS - Reliability

[Signature] 5/21/02
 NASA - EMU/SSM

[Signature] 4/24/02
 HS - Engineering Manager

[Signature] 5/24/02
 NASA - S & MA

[Signature] 5-29-02
 NASA - MOD

 NASA - Crew

 NASA - Program Manager